### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

# WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-016436 Address: 333 Burma Road **Date Inspected:** 25-Aug-2010

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name: CWI Present:** Yes No Xu tao / Li yan hua **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A N/A **Electrode to specification:** No **Weld Procedures Followed:** Yes No Yes N/A **Qualified Welders:** No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component: OBG** Components

## **Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, S.Chandrakumar was present during the times noted above for observations relative to the work being performed. **BAY#19** 

FCAW welding of repair weld joint 2G-037 located on PCMK SB017-084 of SB84W the welder is identified as 062806. ZPMC QC is identified as Mr. Xu tao. The welding variables recorded by QC appeared to Comply with the WPS-345-FCAW-2G (2F)-Repair.

FCAW welding of critical repair weld joint 2G-004 located on PCMK SB019-074 of SB74E the welder is identified as 062783. ZPMC QC is identified as Mr. Xu tao. The welding variables recorded by QC appeared to Comply with the WPS-345-FCAW-2G (2F)-Repair and B-CWR1825.

FCAW welding of critical repair weld joint 3G-019 located on PCMK SB019-074 of SB74E the welder is identified as 062783. ZPMC QC is identified as Mr. Xu tao. The welding variables recorded by QC appeared to Comply with the WPS-345-FCAW-3G (3F)-Repair and B-CWR1825.

FCAW welding of repair weld joint 1G-001 located on PCMK SB016-078 of SB78W the welder is identified as 062757. ZPMC QC is identified as Mr. Xu tao. The welding variables recorded by QC appeared to Comply with the WPS-345-FCAW-1G (1F)-Repair.

Visual inspection of weld joint fit up of bearing plate following weld joints is identified as SB020-084-026,032

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

dimension and tack weld checked with ZPMC Mr. Xu tao is appeared to comply with WPS-B-P-2112.

#### **BAY#14**

SMAW welding of weld joint 4G-019 located on PCMK SEG30042 of Segment 12AW the welder is identified as 051348. ZPMC QC is identified as Mr. Wang xian pin. The welding variables recorded by QC appeared to Comply with the WPS-B-P-2214-Tc-U4b-FCM.

FCAW welding of weld joint 3G-200 located on PCMK SSD25-PP104 of Segment 11DW the welder is identified as 047866. ZPMC QC is identified as Mr. Wang xian pin. The welding variables recorded by QC appeared to Comply with the WPS-B-T-2233-Tc-U4b-F.

FCAW welding of weld joint 2F-115 located on PCMK SSD25-PP104 of Segment 11DW the welder is identified as 202122. ZPMC QC is identified as Mr. Wang xian pin. The welding variables recorded by QC appeared to Comply with the WPS-B-T-2122.

## **BLAST SHOP#1**

Caltrans Quality Assurance (QA) Inspectors performed random visual inspection of OBG segment 11AE Inside corner assembly, Floor beams and Deck panel surfaces from the panel point 95 to 97 after grit blasting. Areas requiring additional grinding were marked by QA and repaired by ZPMC personnel.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

## **Summary of Conversations:**

No relevant Conversation.

### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang-15--0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Kumar,Chadra	Quality Assurance Inspector
Reviewed By:	McClendon, Timothy	QA Reviewer